

AVJ Homes 279 Castlemilk Road Glasgow Scotland G44 4LE

0141 649 3948 sales@avjhomes.com http://www.avjhomes.com/

Property Visit Report

GLASGOW, G44 4LF



Prepared by: Satveer Kaur

AVJ Homes

Report date: 7th October 2023


Living Area(s) Condition

Walls and ceiling	Fair	Flooring	Fair
Photo code: vtv4fxfzu			
Woodwork and doors	Fair	Windows and sills	Fair
		Window is steamed up	
		Photo code: xbnpif3i1	

Living Area(s) – Habitation Checks

Light and electrical fittings	Fair	Leaks or leak damage?	No
Heating	Good	Natural lighting?	Good
Room layout - is it safe / fit for purpose?	Good		





Kitchen Area(s) Condition

Fair	Flooring	Fair
	Photo code: ehaf3zdu3	
Fair	Windows and sills	Poor
Fair	Worktops	Fair
Fair	Appliances	Fair
Fair	Leaks or leak damage?	No
	Fair Fair	Photo code: ehaf3zdu3 Fair Windows and sills Fair Worktops Fair Appliances


Kitchen Area(s) Condition continued

Heating Good

Kitchen Area(s) - Habitation Checks

Mould or damp? No Natural lighting? Fair








Bathroom(s) Condition

Walls and ceiling	Fair	Flooring	Fair
Photo code: 363iqa8ip			
Woodwork and doors	Fair	Windows and sills	Fair
Sanitary ware	Good	Shower and attachments	Fair
		Photo code: 9vnugtppd	
Silicone seals	Fair	Tiles and grout	Fair
Photo code: 95ss1t7ig			
Extractor fan	Fair	Light and electrical fittings	Fair
Leaks or leak damage	No	Heating	Good


Bathroom(s) - Habitation Checks

Mould or damp?	No	Natural lighting?	Fair
Room layout - is it safe / fit for purpose?	Fair		









Bedroom(s) Condition

Bedroom 1

Walls and ceiling	Fair	Flooring	Fair
Photo code: eklfmqwsi			
Windows and sills	Fair	Light and electrical fittings	Fair
Photo code: j01ezfqa2			
Leaks or leak damage?	No	Heating	Good
Wall ventilation clear	Ok		

Bedroom 1 - Habitation Checks

Mould or damp?	No	Natural lighting?	Fair
Room layout – is it safe / fit for purpose?	Good		





Bedroom 2

Walls and ceiling	Fair	Flooring	Fair
Photo code: 2nal38dkg			
Woodwork and doors	Fair	Windows and sills	Fair
		Photo code: xyli41n2e	
Light and electrical fittings	Fair	Leaks or leak damage?	No
Heating	Good	Wall ventilation clear	0k

Bedroom 2 - Habitation Checks

Mould or damp?	No	Natural lighting?	Good
Room layout - is it safe <i>I</i> fit for purpose?	Good		





Smoke Detectors

Smoke detector(s) on eac	h floor? Y	'es		
Location	Expires	Туре	Test Status	Notes
Hallway	-	Mains	Tested, Working	-
Lounge	_	Mains	Tested, Working	-





Heat Detectors

Location	Expires	Туре	Test Status	Notes
Kitchen	-	Mains	Tested, Working	-





CO Detectors

Location Expires Type Test Status Notes

Health and safety detector checks continued

2nd bedroom – Mains Tested, Working –



Health and safety checks			
Property security and locks?	ОК	Boiler housing clear?	No
Animal / insect infestation?	No	Mains fire control panel in property?	No
General Observations			
Ambient odour?	No	Pets?	No
Hoarding?	No	Smoking?	No
Business activity?	No	Malicious damage?	No
Evidence of sub-letting?	No	Attic inspected?	No

Conclusion

Tenant(s) present at inspection? Yes

Signatures

This property inspection report is not a guarantee or report on the accuracy of, or the safety of any equipment or appliance(s) supplied. It is merely a record that such items exist in the property and provides visual recommendations.

Name Satveer Kaur

Date 7th October 2023